

SUBSTATION SWITCHGEAR & PROTECTION (P-85005)

- 1. Testing of the dielectric strength of transformer oil and air.**
- 2. Study of different types of circuit breakers and isolators.**
- 3. Plot the time current characteristics of over current relay.**
- 4. Perform the overload and short circuit test of MCB as per IS specifications.**
- 5. Plot the time-current characteristics of Kit-Kat fuse wire.**
- 6. Taking reading of current on any LT line with clip on meter.**